


1/7

FIG. 1



w_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	0	0	0	0	0	0
						64
					32	32
						96
				16	16	
					80	
			48		48	
					112	
			8	8		
				72		
				40	40	
					104	
		24		24		
				88		
			56	56		
				120		
		4	4	4	4	
					68	
				36	36	
					100	
				20	20	20
						84
			52		52	
					116	
12	12		12	12		
				76		
			44	44		
				108		
	28	28	28			
			92			
60		60				
		124				

FIG. 2B ^{3/7}

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	1	1	1	1	1	1
						65
					33	33
						97
				17	17	17
						81
					49	49
						113
			9	9	9	9
						73
					41	41
						105
				25	25	25
						89
					57	57
						121
		5	5	5	5	5
						69
					37	37
						101
				21	21	21
						85
					53	53
						117
			13	13	13	13
						77
					45	45
						109
				29	29	29
						93
					61	61
						125


w_k^N	N=4	N=8	N=16	N=32	N=64	N=128	
k	2	2	2	2	2	2	
					66		
					34	34	
						98	
				18	18	18	
					82		
			50		50		
					114		
			10	10	10	10	
					74		
					42	42	
					106		
		26		26	26		
				90			
				58	58		
				122			
		6		6	6	6	6
						70	
						38	38
						102	
			22		22	22	
					86		
			54	54	54		
				118			
14	14		14	14			
			78				
			46	46			
			110				
	30	30	30				
		94					
62	62	62					
	126						

FIG. 2D ^{5/7}

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	3	3	3	3	3	3
						67
					35	35
						99
				19	19	19
						83
					51	51
						115
			11	11	11	11
						75
					43	43
						107
				27	27	27
						91
					59	59
						123
		7	7	7	7	7
						71
					39	39
						103
				23	23	23
						87
					55	55
						119
			15	15	15	15
						79
					47	47
						111
				31	31	31
						95
					63	63
						127

6/7

FIG. 3



7/7

FIG. 4